


KEY



Tree to be retained



Tree to be transplanted

Note

All other trees on site to be removed.

Arborist assessment to be undertaken on all trees being retained and transplanted.

Council to undertake cost estimate for protecting trees during construction and transplanting trees.

Trees can not be retained because of car parking restraints
To large to be transplanted.

Trees can not be retained because of car parking restraints

Health of tree has been assessed as poor - to be removed

Trees can not be retained because of car parking restraints
To large to be transplanted.

Tree to be retained (extend proposed planting bed).

Tree to be retained (may need to extend planting bed to allow for paving levels).

Tree to be retained (may need to extend planting bed to allow for paving levels).

Tree to be transplanted to the corner of Cameron Street and West Street

Tree to be transplanted to the corner of Wills Street and West Street

T= Trunk Size (m)
C= Canopy Size (di)

Heights in terms of Lyttelton Datum 1937

Co-ordinates in terms of OCD

Ashburton Museum and Art Gallery
Existing trees - to be retained and transplanted
ISSUED FOR COMMENT
27/04/09



Gallery & Museum Site Survey

LOTS 1, 2, 3, & 4 DP 46522

